


- Do not disassemble the product.
 - As the rotary encoder is composed of precision parts, its function will be impaired when it is



subjected to shocks. Use sufficient care for handling and mounting.

